

Assurance Continuity Maintenance Report

BSI-DSZ-CC-0822-V5-2023-MA-01

SMARTY IQ-LTE, Version 1.3

Hardware Version: DNT8209/3.3/A and DNT8209/3.3/B Software Version 2.1.5003 Operating System Version DNT8233-04

from

Sagemcom Dr. Neuhaus GmbH



SOGIS Recognition Agreement for components up to EAL 4

The IT product identified in this report was assessed according to the procedures on Assurance Continuity [1] and the developer's Impact Analysis Report (IAR). The baseline for this assessment was the Certification Report, the Security Target and the Evaluation Technical Report of the product certified by the Federal Office for Information Security (BSI) under BSI-DSZ-CC-0822-V5-2023.

The certified product itself did not change. The changes are related to a change concerning the certified scope of the delivery procedures.

Considering the nature of the change leads to the conclusion that it is classified as a <u>minor change</u> and that certificate maintenance is the correct path to continuity of assurance.

The resistance to attacks has <u>not</u> been re-assessed in the course of this maintenance process. Therefore, the assurance statement as outlined in the Certification Report BSI-DSZ-CC-0822-V5-2023 dated 10 October 2023 is of relevance and has to be considered when using the product. Details can be found on the following pages.

This report is an addendum to the Certification Report BSI-DSZ-CC-0822-V5-2023.

Common Criteria



Common Criteria Recognition Arrangement recognition for components up to EAL 2 and ALC_FLR only



Bonn, 13 June 2025 The Federal Office for Information Security

Assessment

The IT product identified in this report was assessed according to the procedures on Assurance Continuity [1] and the Impact Analysis Report (IAR) [2]. The baseline for this assessment was the Certification Report of the certified product (Target of Evaluation, TOE) [3], its Security Target and the Evaluation Technical Report as outlined in [3].

The vendor for the SMARTY IQ-LTE, Version 1.3, Sagemcom Dr. Neuhaus GmbH, submitted an IAR [2] to the BSI for approval. The IAR is intended to satisfy the requirements according to the procedures on Assurance Continuity [1]. In accordance with those requirements, the IAR describes (i) the changes made to the certified TOE, (ii) the evidence updated as a result of the changes and (iii) the security impact of the changes.

The certified product itself did not change.

The changes are related to the certified scope of the delivery procedures. The assurance component ALC_DEL.1 (ALC_DEL.1.1D, ALC_DEL.1.1C) has been refined in the ST [4] to only cover the delivery of the TOE from the manufacturer to the MPO (metering point operator), who is the customer of the developer and the recipient of the TOE. Furthermore the service technician, commissioned by the MPO, can now also receive SMGWs directly from the manufacturer.

The further storage and transport of the TOE to the installation environment falls into the responsibility of the MPO and is out of scope of the CC certification.

A related assumption and corresponding security objective for the TOE environment have been added to the ST [4].

The user guidance [5] has been adopted accordingly.

Conclusion

The maintained change is at the level of the delivery procedures. The change has no effect on product assurance, but the updated guidance documentation has to be followed.

Considering the nature of the change leads to the conclusion that it is classified as a minor change and that certificate maintenance is the correct path to continuity of assurance.

The resistance to attacks has <u>not</u> been re-assessed in the course of this maintenance process. Therefore, the assurance statement as outlined in the Certification Report BSI-DSZ-CC-0822-V5-2023 dated 10 October 2023 is of relevance and has to be considered when using the product.

Obligations and notes for the usage of the product:

All aspects of assumptions, threats and policies as outlined in the Security Target not covered by the TOE itself need to be fulfilled by the operational environment of the TOE.

The customer or user of the product shall consider the results of the certification within his system risk management process. In order for the evolution of attack methods and techniques to be covered, he should define the period of time until a re-assessment for the TOE is required and thus requested from the sponsor of the certificate.

Additional Note: The strength of the cryptographic algorithms was not rated in the course of the product certification and this maintenance procedure (see BSIG¹ Section 9, Para. 4, Clause 2).

The foundation for usage of the certificate updated by this maintenance procedure is:

• Use of the latest version of the TOE guidance documentation [5].

This report is an addendum to the Certification Report [3].

¹ Act on the Federal Office for Information Security (BSI-Gesetz - BSIG) of 14 August 2009, Bundesgesetzblatt I p. 2821

References

[1] Common Criteria document "Assurance Continuity: CCRA Requirements", version 3.1, 29 February 2024

Common Criteria document "Assurance Continuity: SOG-IS Requirements", version 1.2, March 2024

- [2] Impact Analysis Report (IAR), Version 1.200, 16 May 2025, Sagemcom Dr. Neuhaus GmbH (confidential document)
- [3] Certification Report BSI-DSZ-CC-0822-V5-2023 for "SMARTY IQ-LTE, Version 1.3", Bundesamt f
 ür Sicherheit in der Informationstechnik, Version 1.0, 10 October 2023
- [4] Security Target BSI-DSZ-CC-0822-V5-2023-MA-01, Version 1.153, 15 May 2025, SMARTY IQ-LTE Security Target, Sagemcom Dr. Neuhaus GmbH
- [5] Sichere Lieferkette, Version 1.200, 16 May 2025, Sagemcom Dr. Neuhaus GmbH